

MOTOR DATA SHEET

Motor type: **Sh500H8D**

Series: High efficiency



08-06-2025

| | ELECTRICAL PARAMETERS | | | | | | | | | | | | | | | | |
|------|-----------------------|----|-----|------|------|------|-----|-------|------|------|------|--------|-------------|-------|-------|---------------|---------|
| U | CONN. | f | F | D | Duty | 1 | n | Т | TL/T | TB/T | IL/I | Effici | ency at loa | d [%] | Power | r factor at l | oad [-] |
| V | - | Hz | kW | HP | - | Α | rpm | Nm | - | - | - | 2/4 | 3/4 | 4/4 | 2/4 | 3/4 | 4/4 |
| 6000 | Y | 50 | 800 | 1080 | S1 | 97.2 | 746 | 10241 | 1 | 2.4 | 6.5 | - | - | 96.6 | - | - | 0.82 |

| GENERAL DATA | | | | | |
|----------------------------|------------|--------------------------------------|--------------------------------|--|--|
| Efficiency class | - | Sound pressure level [dB] | 80 | | |
| Frame size | 500 | Sound power level [dB] | - | | |
| Number of poles | 8 | Terminal box position | top/ * side | | |
| Starting method | DOL | Possibility of terminal box rotation | yes | | |
| Insulation class | F | Bearing on D-side | NU226EM1+6226MC3 / *6326MC3 | | |
| Frequency converter supply | on demand | Bearing on ND-side | NU226EM1/*QJ326N2MPA | | |
| Mounting arrangement | B3/B35/V1* | Bearings regreasing | yes | | |
| Cooling method | IC411 | Housing - material | cast iron | | |
| Weight (IMB3) [kg] | 6890 | Feet - material | cast iron | | |
| Moment of inertia [kgm2] | 94.6 | Bearing shields - material | cast iron | | |
| Direction of rotation | CW/CCW | Painting | RAL5010 | | |
| Degree of protection | IP55 | Climatic execution | N | | |

| ENVIRONMENTAL CONDITIONS | | | | | |
|--------------------------|---|--|------------|--|--|
| Ambient temperature [°C] | from -20 up to +40 Altitude above sea level [m] | | up to 1000 | | |
| Relative humidity [%] | up to 95 | | | | |

| ACCESSORY | | | | | |
|--------------------------------|--------------------------|---------------------------------|--------------------------|--|--|
| Number of terminals or cables | 3 | Temperature sensors in bearings | 2 x Pt100 (1 pc/bearing) | | |
| Cable glands/inlets | 1 | Winding heaters | on demand | | |
| Temperature sensors in winding | 6 x Pt100 (2 pcs./phase) | Optional accessories | on demand | | |

| STANDARDS | | | |
|-----------|-------------|--|--|
| | IEC 60034-1 | | |

| CERTIFICATES | | | | |
|--------------|-------|--|--|--|
| on de | emand | | | |

