

MOTOR DATA SHEET

Motor type: **Sh500H12C**

Series: **HIGH EFFICIENCY**



13-04-2025

| | ELECTRICAL PARAMETERS | | | | | | | | | | | | | | | | |
|------|-----------------------|----|-----|-----|------|------|-----|------|------|------|------|--------|-------------|-------|-------|---------------|---------|
| U | CONN. | f | ŀ | D | Duty | 1 | n | Т | TL/T | TB/T | IL/I | Effici | ency at loa | d [%] | Power | r factor at l | oad [-] |
| V | - | Hz | kW | HP | - | Α | rpm | Nm | - | - | - | 2/4 | 3/4 | 4/4 | 2/4 | 3/4 | 4/4 |
| 6000 | Y | 50 | 400 | 540 | S1 | 49.3 | 495 | 7717 | 0.9 | 2.3 | 5.6 | - | - | 95.3 | - | - | 0.82 |

| GENERAL DATA | | | | | | |
|----------------------------|------------|--------------------------------------|--------------------------------|--|--|--|
| Efficiency class | - | Sound pressure level [dB] | 75 | | | |
| Frame size | 500 | Sound power level [dB] | - | | | |
| Number of poles | 12 | Terminal box position | top/ * side | | | |
| Starting method | DOL | Possibility of terminal box rotation | yes | | | |
| Insulation class | F | Bearing on D-side | NU226EM1+6226MC3 / *6326MC3 | | | |
| Frequency converter supply | on demand | Bearing on ND-side | NU226EM1/*QJ326N2MPA | | | |
| Mounting arrangement | B3/B35/V1* | Bearings regreasing | yes | | | |
| Cooling method | IC411 | Housing - material | cast iron | | | |
| Weight (IMB3) [kg] | 5770 | Feet - material | cast iron | | | |
| Moment of inertia [kgm2] | 72 | Bearing shields - material | cast iron | | | |
| Direction of rotation | CW/CCW | Painting | RAL5010 | | | |
| Degree of protection | IP55 | Climatic execution | N | | | |

| ENVIRONMENTAL CONDITIONS | | | | | | | |
|--------------------------|--------------------|------------------------------|------------|--|--|--|--|
| Ambient temperature [°C] | from -20 up to +40 | Altitude above sea level [m] | up to 1000 | | | | |
| Relative humidity [%] | up to 95 | | | | | | |

| ACCESSORY | | | | | | | |
|--------------------------------|--------------------------|---------------------------------|--------------------------|--|--|--|--|
| Number of terminals or cables | 3 | Temperature sensors in bearings | 2 x Pt100 (1 pc/bearing) | | | | |
| Cable glands/inlets | 1 | Winding heaters | on demand | | | | |
| Temperature sensors in winding | 6 x Pt100 (2 pcs./phase) | Optional accessories | on demand | | | | |

| STANDARDS | | | | | |
|-----------|-------------|--|--|--|--|
| | IEC 60034-1 | | | | |

| CERTIFICATES | | | | | |
|--------------|--|--|--|--|--|
| on demand | | | | | |

